

SQAS Attestation

Safety and Quality Assessment for Sustainability

InfraLeuna GmbH

Report: 92691
Date: 11/09/2024
Location: Germany, Leuna


Module: Tank Cleaning
Expiration Date: 11/09/2027
Assessor: S. Brand

Summary Report

Overall score of the company: 90%

Industry Range of scores per section

This chart shows the average scores of every SQAS section and the European average scores of every SQAS section of all companies with active reports that belong to the same SQAS module and the same questionnaire version



The SQAS summary report is a statement of facts and this does not express any appreciation of the company's performance. The SQAS assessment is valid for 3 years.

